


## Toolbar Buttons Used in the Viewer, Browser and Scrapbook Windows



- ① The Monitor Configuration button is available only in the main Viewer window.
- ② These buttons are not available in the main Viewer window.
- ③ There are several annotation/measurement tools available; to select a different tool, click the arrow next to the button.

## Expanded Annotation Buttons

The Drawing tool displaying its Text icon

The Show/Hide tool displaying its Show All Annotations icon

The Angle Measuring tool displaying its Cobb Angle icon

The Hounsfield Area Measuring tool displaying its Rectangle icon

**Text**  
Line  
Arrow  
Rectangle  
Ellipse  
Free Hand  
Auto Number

**Show Session Annotations**  
**Show Stored Annotations**  
 **Show All Annotations**

**Angle**  
Cobb Angle

**Rectangle**  
Ellipse  
Free Hand

**Annotation Tools**  
A down arrow ▼ adjacent to a toolbar button indicates more options. The appearance of each button will change according to which of its tools is currently selected. To access its other functions, click the arrow to the right of each Annotation tool.